Southampton City Council

City Characterisation Project

# PA07 St Mary's Road (Commercial core)

### Context

- This area lies immediately east of CA32: Solent University, Charlotte Place and environs. To the east and south is PA8: Newtown and Queensland.
- St Mary's Road is the small commercial core of this part of Southampton.
- The land is steadily rising from south to north and there is a sharp level change between this area and Charlotte Place to the west.

## Grain

- Fine grain.
- Consistent building lines to the back edge of pavement.
- Roofs pitched to the road, ridges parallel.

#### Scale

Traditional grand three storey.

#### Uses

- Former Drill Hall now leisure centre.
- Purpose-built late nineteenth century shops with residential accommodation above.
- Residential accommodation converted to offices.
- Nightclub.
- Furniture storage.
- Public house/bar.

## **Public Realm**

The public realm is in poor condition with standard materials, excessive signage, over-engineered traffic junctions and no trees or areas of soft landscaping.

## Connectivity

The area is well-connected to its neighbours with a traditional grid street pattern feeding into the residential suburbs to the north, east and south.

### Views

Towards the southern end of this character area there is a distant view to the football stadium along Brinton's Road.

#### **Building types**

- Purpose-built Victorian shops with accommodation above.
- Drill Hall.



The former drill hall (seen with the crenellated tower) is a memorable building in the townscape

### **Architectural qualities**

- This road has a high degree of architectural quality despite being in a very poor state of repair and with much alteration to ground floor shops and to windows.
- The former Drill Hall is a striking building in the street scene with its crenellated tower forming a strong central feature in the facade.

### Heritage assets

- Victorian terraces of 1899.
- Former Drill Hall 1869.

## Materials

Red brick, natural slate has largely been replaced with concrete interlocking tiles.

## Condition

Very poor.

## Ownership

Private, small businesses, possible high degree of absent landlords.

#### Intervention

Much needed improvements to the design and material quality for shopfronts and signage.

#### Key design principles

Must ensure that future development to the west side of St Mary's Road respects the scale, rhythm and plot division seen on the east side of the road.